


TURN INDICATOR AND WIPER STALK SWITCHES



INDICATOR AND WIPER STALK SWITCHES

NO.	PART NO.	DESCRIPTION	LUCAS	QTY	REMARKS
1	2A6215	Indicator switch	31945E	1	MKI - NLA-
2	47H5200	Green indicator lens		1	MKI
3	6LB290	Bulb for indicator switch		1	MKI
4	13H1773	Horn indicator switch (no wiring plug)	35840M	1	MKII
5	13H1779	Horn indicator switch (with wiring plug)	35384M	1	MKIII
6	21A2658	Indicator switch R/H side	30443H	1	1976 to 1984
6	21A2660	Indicator switch L/H side	30445J	1	1984-1989 plus all LHD
6	BAU5345	Indicator switch L/H side	35483A	1	1989 on
7	37H8285	Wiper switch L/H side	30444H	1	1976-1984
7	37H8286	Wiper switch R/H side	30449H	1	1984-1989 plus all LHD
7	BAU5346	Wiper switch R/H side	35485A	1	1989 on
8	REP01	Repair Kit (not factory), requires modifications to		1	

10

MAINELECTRICAL CHANGE POINTS

Wipers had 3 wires up to 1968
 Wipers had 4 wires and plug 1968 on
 Alternators were fitted 1972 on
 Steering lock fitted 1970 on except 850cc
 Indicator arm with headlamp flashers introduced 1968-70
 Indicator arm with flasher and plug fitted on wires 1970-76
 Indicator and washer stalks 1976 on
 Brake light switch moved to under brake pedal 1976 on
 Rear loom reverse lamp incorporated in rear lamp 1977 on approx