


## Headlamp



## HEADLAMPS

| NO. | PART NO. | DESCRIPTION  | QTY | REMARKS          |
|-----|----------|--|-----|------------------|
| 1   | BHM7196  | Headlamp assembly without side light (Clubman)         | 2   |                  |
| 1   | BHM7198  | Headlamp assembly left dip sealed beam, with side lamp | 2   |                  |
| 1   | S5819    | Headlamp assembly, plastic bucket                      | 2   | LHD              |
| 2   | MS14     | Metal headlamp bowl                                    | 2   |                  |
| 2   | S5400    | Plastic inner rim and seal                             | 2   |                  |
| 3   | MS14K    | Headlamp adjuster kit                                  | 2   |                  |
| 4   | BAU2111  | Bulb holder and connector                              | 2   |                  |
| 5   | GLB501   | Bulb   | 2   |                  |
| 6   | 13H3471A | Sealed beam unit left dip                              | 2   | RHD              |
| 6   | S4698B   | Wipac Quadoptic light kit left dip                     | 1   | RHD              |
| 6   | S4698B   | Wipac Quadoptic light kit right dip                    | 1   | LHD              |
| 6   | S4701    | Quadoptic light unit left dip                          | 2   | LHD              |
| 5   | 6014     | Sealed beam headlamp, Wagner USA                       | 2   | LHD              |
| 5   | 6024     | Sealed beam headlamp, Wagner USA, Halogen              | 2   | LHD              |
| 7   | MS13     | Chrome inner ring and lamp retainer                    | 2   |                  |
| 8   | 515216A  | Inner rim to retain sealed beam                        | 2   |                  |
| 9   | 57H4566  | Headlamp sealing rubber                                | 2   |                  |
| 10  | ADU4278  | Rivet, headlamp to wing                                | 8   |                  |
| 11  | 500929   | Headlamp rim   | 2   |                  |
| 11  | 500920MS | Headlamp rim   | 2   | Aftermarket      |
| 12  | RT1C465  | Headlamp rim screw                                     | 2   |                  |
| 13  | Z7H5981A | Lucas European head lamp glass, was GLU515             | 2   | NLA              |
| 13  | XCC100D1 | Headlamp glass unit                                    | 2   | Optional 1990 on |
| 14  | GLB472   | Headlamp bulb  | 2   | Optional 1990 on |
| 15  | 600226   | Bulb holder (600226A takes GLB410 bulb, L/H)           | 2   | Optional 1990 on |
| 16  | GLB233   | Side lamp bulb   | 2   | Optional 1990 on |
| 17  | BBU1738  | Side lamp bulb holder                                  | 2   | Optional 1990 on |
| 18  | 37H7587  | Cibie headlamp assembly less rim                       | 2   | NLA              |
| 19  | 37H7589A | Cibie light unit was GLU600                            | 2   | NLA              |
| 20  | GLB410   | Bulb, also fits Z7H5981A European                      | 2   |                  |
| 21  | GLB233   | Pilot light bulb                                       | 2   |                  |
| 22  | 37H7588  | Cibie lamp rim   | 2   | NLA              |